


# **IMPROVE**

## **Particle Monitoring Network: Status Report to IMPROVE Steering Committee**

---

Chuck McDade  
Crocker Nuclear Laboratory  
University of California, Davis  
Presented at Incline Village, Nevada  
October 2012




CROCKER NUCLEAR LABORATORY  
University of California, Davis




# IMPROVE Network

## Fall 2012



CROCKER NUCLEAR LABORATORY  
University of California, Davis






# Site Move, October 2011

## RICR1 to FLTO1




CROCKER NUCLEAR LABORATORY  
University of California, Davis





# View from RICR1




CROCKER NUCLEAR LABORATORY  
University of California, Davis





# View from FLT01



CROCKER NUCLEAR LABORATORY  
University of California, Davis








# Site Move, December 2011

## LYBR1 to LYEB1



CROCKER NUCLEAR LABORATORY  
University of California, Davis





# View from LYBR1




CROCKER NUCLEAR LABORATORY  
University of California, Davis







# View from LYEB1



CROCKER NUCLEAR LABORATORY  
University of California, Davis




06/21/2012







# San Gabriel Site Replaced in September 2011



CROCKER NUCLEAR LABORATORY  
University of California, Davis






# UC DAVIS RESPONSES TO EPA FIELD AUDITS



# Audit Summary for 2011




- 28 audits conducted in 2011
  - Flowrate measurement differences exceeded 10% limit in two audits.
  - Nominal flow differed by 11% in one audit but flowrate measurement was in perfect agreement.
  - UCD responses on following slides.






# Lake Sugema, IA, 10/26/11



- D Mod flow high by 17% in audit.
- UC Davis mail audit on 11/28/11 confirmed this result (20% difference).
- Difference was due to a damaged valve. D Mod was replaced on 12/13/11.



# Ike's Backbone, AZ, 10/26/11




CROCKER NUCLEAR LABORATORY  
University of California, Davis

- B Mod nominal flow high by 11% in audit, although flow calibration showed perfect agreement.
- UC Davis check showed nominal flow within 5%, but B Mod was adjusted and recalibrated for good measure on 11/15/11.
- No repairs necessary.



# Ripple Creek, CO, 10/5/11



- A Mod flow high by 10% in audit.
- Site was moved to Flat Tops later in October. Final calibration check at RICR1 shutdown showed A Mod flow to agree with prior calibration (July 2011) to within 1%.
- No backdating or remedial action needed.







# UC DAVIS DATA SUBMITTAL



# Data Submittal Status



- Data have been submitted through October 2011
- November/December data will be submitted by mid-November
- We are analyzing  $>1$  month of samples in each calendar month, expect to reach minimum lag time sometime in late 2013.




# NETWORK PERFORMANCE: CALENDAR YEAR 2011






# 2011 Sample Recovery (A Channel, PM<sub>2.5</sub> Teflon)



- 93% Q1
  - 93% Q2
  - 92% Q3
  - 94% Q4
  - 93% Annual A Channel
- 2009 was 94%, 2010 was 95%




# 2011 Sample Recovery (All channels, ABCD)



- 90% Q1
  - 90% Q2
  - 90% Q3
  - 93% Q4
  - 91% Annual ABCD
- 2009 was 91%, 2010 was 93%



# Reasons for Sample Losses




Of the 9% of lost samples (ABCD):

- 29% Equipment problems
- 28% Operator no-show
- 17% Power outages
- 10% Incorrect filter cassette installation
- 16% Torn or damaged filter



# Regional Haze Rule Requirements



A “complete” site has, for ABCD:


- >75% annual recovery
- >50% recovery in each quarter
- <11 consecutive missed samples

7 sites failed in 2011

(4 in '06, 7 in '07, 13 in '08, 11 in '09, 9 in '10)



# Sites Failing RHR Requirements: Weather




- Fort Peck, MT (Protocol)
  - Failed consecutive samples
  - Snowed in, inaccessible
- Thunder Basin, WY (Protocol)
  - Failed first quarter
  - Snowed in, inaccessible
  - Also failed in '08 (snow), '09 (operator problems), '10 (operator & controller problems)
- Gila Cliff Dwellings, NM (IMPROVE)
  - Failed annual criterion
  - 4 separate lightning strikes, also Miller Fire






# Sites Failing RHR Requirements: Missed Sample Changes



- Lostwood, ND (IMPROVE)
  - Failed second quarter
  - Lost primary operator, then new operator missed many samples and installed others incorrectly
- Sierra Ancha, AZ (IMPROVE)
  - Failed annual criterion
  - Fire fighting duties and insufficient backup operators
- Remedy for missed sample changes
  - Discuss problem with operator and/or supervisor. Both of these sites have improved their site visitation in 2012.




# Sites Failing RHR Requirements: Equipment Problems



- Gates of the Mountains, MT (IMPROVE)
  - Failed first quarter and consecutive criteria
  - Controller damaged on first sample of box. 3 weeks of urban-schedule sampling (30 min/hr); operator was unaware
  - Also failed in 2010 due to missed samples and lightning
- Zion Canyon, UT (IMPROVE)
  - Failed fourth quarter and annual criteria
  - Controller & pump problems, compounded by lack of operator communication. Power outages throughout the year.
  - Also failed in 2010 due to late notification of problems.
  - Operator has been instructed to report problems promptly.



# Additional 2012 RHR Failures due to PM-10 Module Anodizing Dust



- Columbia Gorge, WA (Protocol)
- Douglas, AZ (Protocol)
- Meadview, AZ (Protocol)
- North Absaroka, WY (IMPROVE)
- Salt Creek, NM (IMPROVE)
- White Mountain, NM (IMPROVE)






# Anodizing dust was observed on some PM-10 filters



CROCKER NUCLEAR LABORATORY  
University of California, Davis













# Anodizing Dust



- Observed at 14 sites
- First noted in April 2012, apparently began in 2011
- Dust is due to abrasion of the PM-10 stack
- Remedy:
  - Install tripods to stabilize stacks and avoid twisting in wind.
  - Add an o-ring to avoid metal-to-metal contact.
  - Label stacks to be installed at proper height, to avoid metal-to-metal contact at base of stack.
  - Inspect every PM-10 sample in 2011 and 2012. Flag or invalidate data from affected samplers.



# Tripod stabilizes the stack




CROCKER NUCLEAR LABORATORY  
University of California, Davis






# O-ring avoids metal-to metal contact



CROCKER NUCLEAR LABORATORY  
University of California, Davis



Funnel



# New label indicates proper stack positioning



CROCKER NUCLEAR LABORATORY  
University of California, Davis

